

TMC SPECIFICATION

NO. S 1068

REV:

ØA

COMPILED: *MHS 2/4/66*

CHECKED:

JG 2/4

APPD:

[Signature]

SHEET

1

OF

5

TITLE:

LPP-3-2 TEST PROCEDURE

TMC SPECIFICATION

NO. S 1068

REV: A

COMPILED:

CHECKED:

APPD:

SHEET 2 OF 5

TITLE: LPP-3-2 TEST PROCEDURE

I. EQUIPMENT REQUIRED

1. One Simpson Meter, No. 260 or equivalent.
2. One PJ 055. plug.
3. 6" length MWC22/7/U0.
4. 6" length MWC22/7/U2.
5. One CK1092. (Schematic Diagram)

II. PRELIMINARY

1. Remove covers and inspect for poor solder joints; check for mechanical defects.

III. PROCEDURE

1. Connect red wire to tip of PJ055 and black wire to sleeve of PJ055.
- * 2. Plug into J1. Connect meter between ground and the red and black wire. Set meter on RX100 scale. Meter should read "infinity". Repeat for all other jacks.
- * 3. Connect meter between red and black wire. Insert plug in J1. Meter should read "infinity". Repeat for all other jacks.
- * 4. Connect meter to black wire on PJ055 and other side to E3-12. Set meter on R x 1 scale. Plug jack into J1, 2, 3 and 4. Meter should read "zero".
- * 5. Repeat with appropriate sets of four (4) jacks and terminal pin.
- * 6. Connect meter between red lead of plug and E3-11. INSERT PLUG IN J1 and J3. Meter should read "zero".
- * 7. Repeat with appropriate pairs of jacks up to J12, skip J13 thru J16 and continue thru J38 and J40.
- * 8. Place meter between E3-11 and E6-8. Meter should read "zero". Place open plug in J1. Meter should read "infinity". (Do not permit plug wires to touch.)
- * 9. Repeat for line jacks up to J10; skip J13 and J14 and continue to J38 between appropriate terminals.

TMC SPECIFICATION

NO. S 1068

REV: **A**

COMPILED:

CHECKED:

APPD:

SHEET

3

OF

5

TITLE:

LPP-3-2 TEST PROCEDURE

- * 10. Connect meter between E1-5 and red lead of plug. INSERT plug into J41. Meter should read "zero".
- * 11. Repeat for J15, J13, J43, J45, J47 using appropriate terminals.
- * 12. Connect meter between E1-4 and E4-3. Meter should read "zero". INSERT plug in J42. Meter should read "infinity". Repeat with J43 and J44.
- * 13. Connect meter between E1-1 and E4-1. Meter should read "zero". Insert plug in J46, 47, and 48. Meter should read "infinity".
- * 14. Connect meter between E1-5 and E4-4. Meter should read "zero". INSERT plug in J41. Meter should read "infinity".
- * 15. Connect meter between E1-2 and E4-2. Meter should read "zero". INSERT plug in J45. Meter should read "infinity".
- * 16. Connect meter between E3-1 and E6-1. Meter should read "zero". INSERT plug in J14, J15, and J16. Meter should read "infinity".
- * 17. Connect meter between E1-2 and E6-2. Meter should read "zero". INSERT plug in J13. Meter should read "infinity".

* RECORD ON TEST DATA SHEET

TMC SPECIFICATION

NO. S S1068

REV: 1

COMPILED:

CHECKED:

APPD:

SHEET 4 OF 5

TITLE: LPP-3-2 TEST PROCEDURE

THE TECHNICAL MATERIEL CORPORATION

MAMARONECK, N.Y.

LPP-3-2 TEST DATA SHEET

SERIAL NO. _____

MFG. NO. _____

PRELIMINARY

STEP 1 _____ OK

PROCEDURE

STEP 2 _____ OK

STEP 10 _____ OK

3 _____ OK

11 _____ OK

4 _____ OK

12 _____ OK

5 _____ OK

13 _____ OK

6 _____ OK

14 _____ OK

7 _____ OK

15 _____ OK

8 _____ OK

16 _____ OK

9 _____ OK

17 _____ OK

DATE: _____

TESTER: _____

