





# TMC SPECIFICATION

NO. S 1247

REV:

Ø A B

COMPILED: VG

CHECKED:

APPD:

SHEET 2 OF 8

TITLE: ~~INSTALLATION PROCEDURE~~ FOR KIT 322 (Consists of KIT 321 and the following Parts)

#### IV. TOOLS REQUIRED:

1. Screw Driver, Phillips
2. Screw Driver, Blade
3. 5/16 Open End Wrench
4. Drill Motor & 9/64 Drill Bit or means for drilling Relay Mtg. holes (Fig. 1)
5. Soldering Iron & Solder
6. Wire Strippers
7. Long Nose Pliers

#### V. INSTALLATION PROCEDURE

CAUTION - CAUTION - CAUTION

REMOVE ALL AC INPUT TO TRANSMITTER. INSTALL KIT 321 (ITEM 1) BEFORE PROCEEDING WITH MODIFICATION.

1. Pull out 40K bias supply, disconnect inter-connecting cables and remove bias supply from transmitter.
2. Referring to Fig. 3, assemble and mount terminal strip mounting plate in position as shown.
3. Open bias supply connecting plug (P-7105). Using Item 8 as called out in materials supplied, place 1/2 inch of Item 19 on loose ends, solder leads to open Pins "L" and "M" of P7105, White Lead to "L", Black Lead to "M". Push Item 19 into place and secure plug. Dress Item 8 as shown in Fig. 4 securing cable with Item 20 (cable tie-wrap) as necessary and terminate Leads as shown in Fig. 3 using Item 10 (spade lugs).
4. From terminal strip mtg. position (Ref. Fig. 3) connect Item 9 (observe matching leads) and route cable through transmitter as shown in Fig. 4. Terminate leads at the rear of unit AX-5031 Terminals 4 and 5 of TB-101. Secure cable using Item 20, as necessary.

# TMC SPECIFICATION

N . s 1247

REV:

0 A B

COMPILED: VG

CHECKED:

APPD:

SHEET 3 OF 8

TITLE:

INSTALLATION PROCEDURE FOR KIT 322

(Consists of KIT 321 and the following Parts)

5. On 40K bias supply drill four relay mounting holes as shown in Fig. 1. Properly assemble relay mounting plates and mount relay
6. Connect Relay (Item 13) using Item 7. Connect leads as shown in Fig. 2, routing cable through center grommet of chassis. Mount terminal tie point to filter assembly using Items 3, 25, 26, and 27. Ref. Fig. 2A
7. Remove Red Lead from Capacitor C-7512 and solder with Red Lead at tie-point (Item 3). Solder Red/White Lead from relay cable to lug terminal of C-7512. Complete wiring as shown in Fig. 2A. Only relay connecting leads are shown in Fig. 2A use 1/2" of Item 19 on Pins "L" and "M".
8. Place 40K bias supply back into slide position and connect all connecting cables. This completes transmitter modification. Affix (Item 28) near transmitter nameplate.
9. Refer to Section VI of KIT 321 for final tune-up procedure of transmitter.

# TMC SPECIFICATION

NO. S 1247

REV:

Ø A B

COMPILED: VG

CHECKED:

APPD:

SHEET 4 OF 8

TITLE:

KIT 322

40K BIAS SUPPLY (TOP VIEW)




FIG. 1

FRONT PANEL

# TMC SPECIFICATION

NO. S 1247

REV: Ø A B

COMPILED: VG



CHECKED:

APPD:

SHEET 5 OF 8

TITLE:

KIT 322



**FIG. 2A**

BOTTOM VIEW 40K BIAS SUPPLY  
 ONLY RELAY CONNECT CABLE LEADS SHOWN

# TMC SPECIFICATION

NO. S 1247

REV: 0 A B

COMPILED: VG


CHECKED:

APPD:

SHEET 6 OF 8

TITLE:

KIT 322



# TMC SPECIFICATION

NO. S 1247

REV: 0 A B

COMPILED: VG

CHECKED:


APPD:

SHEET 7 OF 8

TITLE:

KIT 322

FIG. 4



REAR OF TRANSMITTER

RANDOM ROUTE OF INTERCONNECT CABLE  
SECURE WITH ITEM 20 AS NECESSARY



# TMC SPECIFICATION

NO. S 1247

REV: 0 A B

COMPILED: VG

CHECKED:


APPD:

SHEET 8 OF 8

TITLE:

*KIT 322*

## 40K BIAS SUPPLY



## BEFORE MODIFICATION

## AFTER MODIFICATION

