

TMC SPECIFICATION NO. S-638

COMPLETED CHECKED

SM
APPROVED

TITLE: KIT-113 - VSWR METERING - 10K

D

KIT-113

VSWR METERING - 10K

| KIT NO. | IMPEDANCE | SECT. III, A ITEM NO. 38 |
|------------|-----------|-----------------------------|
| KIT-113-50 | 50 ohms | NONE REQ. |
| KIT-113-70 | 70 ohms | P6-250 |

DATE 1/12/62

SHEET 1 OF 4

TMC SPECIFICATION NO. S-638 D

COMPILED CHECKED

TITLE: KIT-113 VSWR METERING - 10K

APPROVED

I. EQUIPMENT AFFECTED:

A. GPT-10K Transmitting Set Radio

II. PURPOSE:

A. Modification of Existing GPT-10K's (Field) to Accept a Directional Coupler to Meter the Output Power and S.W.R.

III. MATERIALS SUPPLIED IN THE KIT:

A. Items

| | |
|---|---|
| 1. One each A-2233 | Coupler and Bracket Assembly |
| 2. One each A-2234 | Decoupling Assembly |
| 3. One each LD-990/MS-2699 | Plate, Output Switch |
| 4. One each LD-991/MS-2699 | Plate, Calibrate Pot. |
| 5. One each MP-102-1 | Knob, pointer |
| 6. One each MP-102-2 | Knob |
| 7. One each MR-155 | Meter, output, SWR (Sym. M1005) |
| 8. One each LD-1000 /MS-2752 | Plate, Pot. Mtg. |
| 9. One each RV-108 | Pot., Dual. (Sym. R916A,B) |
| 10. One each SW-111 | Switch, rotary (Sym. S907) |
| 11. One each CA-412-23-24.00 | Cable, Output |
| 12. One each CA-653 | Cable, Switch to Pot. |
| 13. One each CA-654 | Cable, coupler to switch |
| 14. One each ID-266 | Installation KIT-113 |
| 15. One each | Stamp R1007 |
| 16. One each | Stamp R1008 |
| 17. One each | Stamp C1026 |
| 18. One each | Stamp C1027 |
| 19. One each | Stamp pad |
| 20. Two each NTH3732BN16 | Nut, hexagon p/o SW-111, RV-108 |
| 21. Two each LWI37MRN | Washer, lock, internal p/o SW-111, RV-108 |
| 22. One each SCBP0832BN6 | Screw, machine |
| 23. One each FW08HBN | Washer, flat |
| 24. One each LWS08MRN | Washer, lock, split |
| 25. One each NTH0832BN10 | Nut, hexagon |
| 26. Four each SCOP0632BN8 | Screw, machine |
| 27. Three each NTH0632BN8 | Nut, hexagon |
| 28. Three each LWE06MRN | Washer, lock, external |
| 29. Five each SCBP0832BN10 | Screw, machine |
| 30. Five each NTH0832BN10 | Nut, hexagon |
| 31. Five each LWE08MRN | Washer, lock, external |
| 32. Five each FW08HBN | Washer, flat |
| 33. Five each CU-102-3 | Clamp, cable |
| 34. One each | 5/8 inch Greenlee |
| 35. One each | Drill bit, #11/64 inch |
| 36. One each | Drill bit, 3/8 inch |
| 37. One foot WL-100-7 | Wire, Buss, Size 22 |
| * 38. One each P0-250 | Adapter, 50 to 70 bms |
| * Ship Item 3d for KIT-113-70 only. | |

DATE 1/3/64
SHEET 2 OF 4

TMC SPECIFICATION NO. S-638

D

COMPILED

CHECKED

TITLE: KIT-113-VSWR METERING-10K

APPROVED

IV. TOOLS REQUIRED:

A. To be Provided by Installing Activity

1. pliers, 6 inch longnose
2. pliers, 6 inch diagonal cutting
3. Screwdriver, five inch
4. Allen wrench, 8-32
5. Wrench, crescent, ten inch
6. Wrench, open end, 3/8-7/16
7. Wrench, open end, 1/2-9/16
8. Soldering iron, 75 watt
9. Hand drill, 3/8 inch chuck

V. DISASSEMBLY OF GPT-10K

Reference - ID-266

- A. Remove rear door main frame, figure 1. (Save)
- B. Remove front door main frame, figure 1. (Save)
- C. Remove right side panel, figure 1. (Save)
- D. Remove top panel, figure 1. (Save)
- E. Remove outer shield, figure 1. (Save)
- F. Remove inner shield, modify if required for DC-102, clearance figure 1.
- G. Remove cover plate (if applicable) figure 1; discard.
- H. Remove output bracket, figure 1 & 3 discard. Remove window panel, Figure 1 & Save.
- I. Remove control panel shield, figure 1 & 3, and hold for modification per Step P.
- J. Loosen meter panel, figure 1, and remove MR-126 (symbol M1004). Be sure to save the capacitor, C1011, that is across the meter, figures 1 & 2.
- K. Remove the two capacitors, C1020 and C1019, the four jumpers, and the two feed-thrus mounted on the rear of the meter box; figure 2 & 3 (discard all except one jumper that will be used as a ground connection for the new meter).
- L. Remove the unbalanced output cable if necessary. Figure 2 & 3.
- M. Remove the two chokes, L916, L917, and associated stands and brackets; figure 2 & 3. Discard.
- N. Remove the thermocouple, TC900 and associated jumpers (3); figure 3. Discard.

VI. MODIFICATION OF THE EQUIPMENT

- O. Without removing main control panel (figure 1), lay out and drill holes A and B per drill plan No. 1.
- P. Control Panel Shield (Removed in Step I): Use the 5/8 Grease punch supplied (Item 34) to put a slot in the shield as per drilling plan 2.

DATE 1/3/64

SHEET 3 OF 4

TMC SPECIFICATION NO. S-638

D

COMPILED CHECKED

TITLE: KIT-113 - VSWR METERING-10K

APPROVED

VII. REASSEMBLY

- Q. Attach the coupler and bracket assembly, A-2233 (Item 1) in the position from which MS-1605 (figure 1, Step H) was removed.
- R. Insert MR-155 (Item 7) in place of MR-126 (Removed in Step J).
- S. Install the output switch plate, LD-990/MS-2699 and the calibrate pot. plate, LD-991/MS-2699 on the control panel with the 6-32 hardware supplied (Items 26,27,28) per Figure 4. Be sure to put the output switch plate to the right and the calibrate pot. plate to the left. (NOTE: Use two screws, lockwashers and nuts to mount the calibrate pot plate, use one screw, lockwasher and nut to mount the output switch plate in its 1 ft mtg. hole only. Save one screw).
- T. Mount the dual potentiometer, RV-108 (Item 9) and the potentiometer mounting plate, LD-1008/MS-2752 in the calibrate position with the 3/8 inch nut and lock washer (Items 20 & 21). Ref: Figure 4.
- U. Mount the switch, SW-111 (Item 10) and the decoupling assembly, A-2234 (Item 2) in the output position with the 3/8 inch nut and lock washer (Items 20 & 21). Also use the 6-32 screw saved from step S to mount the front plate to the rivet nut in the decoupling assembly bracket. Ref: Figure 4.
- V. Put on the knobs, MP-102-1 and MP-102-2 (Items 5 & 6). Be sure to put the knob with the pointer on the output switch. REF: Figure 4.
- W. Run the cable CA-654 (Item 13) from the coupler assembly, A-2233, to the switch, SW-111, using mounting hardware, Items 29,30,31,32,33. Solder the center conductor of the FWD RF cable to choke L918. Solder the center conductor of the RFL RF cable to the choke L919. Solder the center conductor of the shielded wire to the wiper of the switch and then solder the three shields to ground.
- X. Run the other end of the shielded wire in the cable, CA-654 to the Meter, MR-155. Connect the center conductor to the positive (+) side of the meter, MR-155, and the shield to the negative (-) side. Be sure to replace the capacitor, C1011, across the meter and the jumper from the negative (-) side of the meter to ground.
- Y. Wire the potentiometer, RV-108, and the switch, SW-111 with the cable CA-653 according to the new schematic, figure 2.
- Z. Solder in a jumper (Item 37) between the coil, L918 and the number (1) position of the switch.
- AA. When hacking the circuit be sure that the arrow on the diode of the directional coupler that is metering the forward power is pointed toward the output while the arrow of the other diode is pointed towards the transmitter.

DATE 1/12/62
SHEET 4 OF 4

TMC SPECIFICATION NO. S -638

COMPILED CHECKED

TITLE: KIT-113 - VSWR METERING - 10K


APPROVED

- AB . Using the stamps and stamp pad supplied, (Items 15, 16, 17, 18, & 19) stamp the symbols R1007, R1008, S1026 and G1027 in an appropriate spot near lamp sockets which might have existing stamping now covered by new plates.
- AC . Replace the control panel shield and make sure that the grommet ⁱⁿ ~~is~~ ^{on} the cable, CA-654 is put in the slot that was cut out; figure 4.
- AD . Connect the antenna tuner for unbalanced operation and connect the output cable, CA-412-23-24.00 (Item 11) from E904 to the directional coupler.
- AE . Replace inner-shield; figure 1.
- AF . Replace outer-shield; figure 1.
- AG . Replace top panel; figure 1.
- AH . Replace right side panel; figure 1.
- AI . Replace front and rear doors; figure 1.

VIII. TEST PROCEDURE

To test the directional wattmeter after installation a 0-20 amp. RF ammeter and a 50 ohm 5KW load should be placed in series with it as per Figure below.

DIRECTIONAL WATTMETER



The transmission should be driven until the ammeter reads 10 amps. The wattmeter should then read 5 KW \pm 10% if the load is 50 \pm 10 ohms.

To check the SWR the output switch should be set to calibrate and the meter calibrated. Then set the switch to SWR and the SWR of the output will be read directly. The accuracy can be checked by inserting a known SWR and comparing with the meter reading.

REVISION SHEET

**THE TECHNICAL MATERIEL CORP.
MAMARONECK NEW YORK**

S-638

MODEL KIT-113

PROJECT NO.