DATE 2-27-61 SH. 1 OF 1 COMPILED BY A.R. Faiola		TMC	SPECII	FICAT	ON	NO.
	TITLE:	MOD	IFICATION OF	SB-12a	(FSA)	
APPROVED /			FOR HOE H	/n/r/t/ 2		

- Remove bottom cover of unit. 1.
- 2. Remove wire from pin H on J-402. This wire goes from pin H on J-402 to pin G on J-501.

FOR USE W/PTE-3

S-547

SOL

- 3. Remove jumper from pin I on J-402. This jumper goes from pin I to pin J on J-402. A shielded wire should remain connected to pin J after the removal of this jumper.
- 4. Connect a length of insulated shielded wire (WI-101-2) from pin H on J-402 to pin 7 of V-17. For a neat installation, this wire can be fed through the original main cable of the SB-12a, or it can be laced on to the original main cable. Connect each end of shield to the nearest ground point (I.E. ground lug or tube socket ground strap).
- 5. Connect a length of insulated shielded wire (WI-101-2) from pin I on J-402 to pin 2 of V-15. The same installation can be applied as in step 4. Connect each end of shield to the nearest ground point (I.E. ground lug or tube socket ground strap).
- 6. Replace bottom cover. This completes modification of SB-12a.