



FOR OPERATION WITH PAD  
 1. REMOVE JUMPER MARKED \*\*\* BETWEEN R622 & T602.  
 2. ASSEMBLE RESISTORS R621, R622, R623 AS PER INSTRUCTION MANUAL.

LAST SYMBOLS	MISSING SYMBOLS
C611	P602
CR602	W601
F602	
I602	
J606	
L603	
M601	
Q603	
R625	
S601	
T604	
Z602	

UNLESS OTHERWISE SPECIFIED  
 ALL CAPACITORS ARE IN MICROFARADS.  
 ALL COIL ARE IN MICROHENRIES.  
 ALL RESISTORS ARE 1/2 WATT.

FOR 230V OPERATION T601  
 1. REMOVE JUMPERS FROM TERMINALS 1, 2 & 3, 4.  
 2. ADD JUMPER MARKED --- BETWEEN TERMINALS, 2 & 3.

REQ.	ITEM	PART NO.	DESCRIPTION	SYMBOL
THE TECHNICAL MATERIEL CORP. MAMARONECK, NEW YORK				
CONTROL, SYNTH., STANDARD				
D. J. MANN				
DRAWN		CHECKED		FINAL APPROVAL
CK-441 F				
SHEET OF				

REQ. PER UNIT	MODEL	SECTION	ASS'Y. NO.	DATE
	CSS-1			12-10-60
USED ON				