

TMC SPECIFICATION

NO. S 1046

REV:

COMPILED: *LS, 12/9/65*

CHECKED: *LS*

APPD: *LS*

SHEET 1 OF 2

TITLE: TTR-10 TO TTR-12 LIST CONVERSION

51046

I. TO CONVERT A TTR-10 TO A TTR-12 FOR USE WITH THE TPCA-1, MAKE THE FOLLOWING CHANGES:

A. On TTR-10 List (To convert to TTR-12)

1. Chg AX418 to AX418-3; MAIN CHAS ASSY.
2. Chg all A2792 Refs and U/O to A2792-3.
3. Add 1 ea CK1079; DIAG,INTCON.

B. On AX418 List (To convert to AX418-3)

1. Dele 1 ea DT108; DETENT, SW-30DEG; U/O A4045.
2. Dele 1 ea LD1644/MS4113; PL,DETENT; U/O A4045.
3. Dele 1 ea MS4113; PL,DETENT; U/O LD1644.
4. Dele 1 ea MS4167; COV,TB CUTOUT; U/O AX418.
5. Dele 1 ea A4045; DETENT ASSY, REAR; U/O AX418.
6. On LWE04MRN, Chg U/T/M fr MS4167 (4) to TM100-11 (3); Chg Qty fr 150 to 149.
7. On LWE06MRN, Chg U/T/M fr A4045 (4) to SW380 (4).
8. Add 2 ea MS154-1,; U/O AX418-3; Chg Qty fr 4 to 6.
9. On NTH0440BN8, Chg U/T/M fr MS4167 (4) to TM100-11 (4).
10. Add 1 ea PX337-11; INS, TERM.BD; U/O AX418-3, U/T/M TM100-11.
11. Chg SCBP0440BN5 qty fr 20 to 16; Dele U/T/M MS4167; Chg U/O AX418 Qty fr 6 to 2.
12. Add 4 ea SCBP0440BN10; U/T/M TM100-11; U/O AX418-3; Chg Qty fr 8 to 12.
13. On SCBP0632BN5, Chg U/T/M fr A4045 (4) to SW380 (4).
14. Add 1 ea SW380; SW-SOL,ROT.; U/O AX418-3; Sym S1515.
15. Add 1 ea TE104-1; TERM.,LUG-NO.4; U/T/M TM100-11; U/O AX418-3.
16. Add 1 ea TM100-11; TERM.BD-BARR; U/O AX418-3; Sym TB1502.

TMC SPECIFICATION

NO. S 1046

REV:

COMPILED:

CHECKED:

APPD:

SHEET 2 OF 2

TITLE: TTR-10 TO TTR-12 LIST CONVERSION

17. Add 1 ea 1N547; SCOND DEV,DIO; U/O AX418-3; For SW380; Sym CR1502.
 18. Add 12 ea MWC24/7/U0; WIRE,ELEC,INS; U/O CA
 19. Add 12 ea MWC24/7/U1; WIRE,ELEC,INS; U/O CA
 20. Add 12 ea MWC24/7/U2; WIRE,ELEC,INS; U/O CA
 21. Add 12 ea MWC24/7/U3; WIRE,ELEC,INS; U/O CA
 22. Add 12 ea MWC24/7/U4; WIRE,ELEC,INS; U/O CA
 23. Add 12 ea MWC24/7/U5; WIRE,ELEC,INS; U/O CA
 24. Add 12 ea MWC24/7/U6; WIRE,ELEC,INS; U/O CA
 25. Add 12 ea MWC24/7/U7; WIRE,ELEC,INS; U/O CA
 26. Add 12 ea MWC24/7/U9; WIRE,ELEC,INS; U/O CA
 27. Add CD101-1MW; U/O CA
 28. Add 1 ea CK1079; DIAG,INTCON.
 29. Chg all AX418 refs and U/O to AX418-3.
 30. Add 1 ea CA ; WRG HARN,SW.
- C. Ref Mod KIT-278.