

TMC SPECIFICATION

NO. S 1176

REV: 0

COMPILED: RRH

CHECKED:

APPD: *[Signature]*

SHEET 1 OF 2

TITLE:

typed by vita

3/14/67

INSTRUCTIONS

for

CONVERSION OF GPR-90RXDS TO GPR-91RXDS

TMC SPECIFICATION

NO. S 1176

REV: 0

COMPILED: RRH

CHECKED:

APPD:

SHEET 2 OF 2

TITLE: INSTRUCTIONS FOR CONV. OF GPR-90RXDS TO GPR-91RXDS

typed by vita 3/14/67

1. Remove ground connections from T3 terminal (coded ORANGE) and T4 terminal, (coded BLACK).
2. Add ground connection to terminal of T2 (coded YELLOW).
3. Remove A-1034 from use as T5 and substitute TT-192.
4. Remove A-1039 from use as T6 and T7, and substitute TT-191.
5. Test and align in accordance with S-771.

PARTS LIST

<u>QTY</u>	<u>TMC PART NO.</u>	<u>DESCRIPTION</u>
1	TT-192	IF Transformer
2	TT-191	IF Transformer
1	S-771	Test & Alignment Specification

