

S1048

TMC SPECIFICATION

NO. S 1048

REV: Q

COMPILED: A. KLEIN 12/8

CHECKED: Zg, 12/8/65

APPD: Zg [Signature]

SHEET 1 OF 2

TITLE: SBC-1A TO SBC-8 LIST CONVERSION

I. TO CONVERT SBC-1A TO SBC-8, MAKE THE FOLLOWING CHANGES:

A. On SBC-1A List (To convert to SBC-8)

1. Chg 1 ea AFC-2A to AFC-8.
2. Chg 1 ea SBS-1 to SBS-8.
3. Chg 1 ea S649 to S1043, Test Proc.

B. On AFC-2A List (To convert to AFC-8)

1. Add 1 ea CL275-101; COIL,RF,FXD; Sym L5017; u/o A2447-6.
2. Dele 1 ea CL275-151; Chg qty from 3 to 2; COIL,RF,FXD; dele Sym L5017; u/o A2447-5.
3. Add 1 ea CM15C200J03; CAP.,FXD,MICA; Sym C5105; u/o A2447-6.
4. Dele 1 ea CM15C220K; CAP.,FXD,MICA; Sym C5105; u/o A2447-5.
5. Add 1 ea CM15C510J03; CAP.,FXD,MICA; Sym C5106; u/o A2447-6.
6. Dele 1 ea CM15C820K; Chg qty from 2 to 1; dele Sym C5106; u/o A2447-5.
7. Chg 1 ea CR109-4 to CR109-85; XTAL UNIT,QTZ; 10.350 MC; Sym Y5003; u/o A2447-6.
8. Chg 1 ea NF107-705 to NF107-350; Sym Z5002 (NPL).
9. Chg 1 ea NF108-705 to NF108-350, Sym Z5001 (NPL).
10. Chg 1 ea NF110-705 to NF110-350, Sym Z5003 (NPL).
11. Chg 1 ea A2447-5 to A2447-6; Sym A5000.
12. Chg 1 ea AO112 to AO112-2 and OVEN ASSY, HF,705 KC to OVEN ASSY HF,350 KC; Sym Z5005.
13. Chg all refs and u/o from A2447-5 to A2447-6.
14. Chg all refs and u/o from AO112 to AO112-2.

C. On SBS-1 List (To convert to SBS-8)

1. Chg SBS-1/MAIN to SBS-8/MAIN.
2. Chg 1 ea S705 to S1047.
3. Chg all refs and u/o from SBS-1 to SBS-8.

TMC SPECIFICATION

NO. S 1048

REV:

COMPILED:

CHECKED:

APPD: *Mickey*

SHEET

2

OF

2

TITLE:

SBC-1A TO SBC-8 LIST CONVERSION

D. On SBS-1/MAIN List (To convert to SBS-8/MAIN)

1. Chg CM15B221K; CAP.,FXD,MICA; Qty from 2 to 1; dele Sym C6217.
2. Chg 1 ea CM15B241K to CM15F301J03; CAP.,FXD,MICA; Sym C6216;
u/o A2362
3. Chg 1 ea CM15B330K to CM15B100K03 ; CAP.,FXD,MICA; Sym C6215;
u/o A2362.
4. Add 1 ea CM20F561G03; CAP.,FXD,MICA; Sym C6217; u/o A2362.
5. Chg 1 ea CR109-77 to CR47A/U350.000KC; XTAL UNIT,QTZ; 350KCS;
Sym Y6200.

