

TMC SPECIFICATION

NO. S 939

REV: **A**

COMPILED: L.G. 5-7-65

CHECKED: *L. J. J. 5/7*APPD: *J. J. J.*

SHEET 1 OF 2

TITLE: CHGR-3 to CHGR-3A CONVERSION

1. TO CONVERT THE CHGR-3 TO THE CHGR-3A, MAKE THE FOLLOWING CHANGES.

A. ON LIST CHG-3/CHGR-3

1. DELETE B1110-7; U/O A4146; QTY. 1; SYMBOL DS1006.
2. DELETE LD1744/MS4268; PNL, FRONT; QTY 1.
3. DELETE MS4268; PNL, FRONT; QTY 1.
4. DELETE MP123-5FB; U/O A4146; QTY. 1.
5. DELETE RC32GF221K; U/O A4146; QTY. 1; SYMBOL R1065.
6. DELETE TS153-1; U/O A4146; QTY. 1; SYMBOL XDS1006.
7. DELETE A4146; PNL ASSY, FR. ; QTY. 1.
8. DELETE CK922; DIAG, SCHEM. ; QTY. 1.
9. ADD LD1836/MS4460; PNL, FRONT: U/O A4227; QTY. 1.
10. ADD MS4460; PNL, FRONT: U/O LD1836; QTY. 1.
11. ADD A4227; PNL ASSY, FR; U/O A2944; QTY. 1.
12. ADD CK966; DIAG, SCHEM; U/O CHGR-3A; QTY. 1.
13. ADD NT153-1; NUT, CAP ; U/O A4227; QTY. 1.
14. CHANGE ALL U/O REFERENCES FROM A4146 TO A4227.

B. ON LIST AX556

1. DELETE A1301 FROM LAST SYMBOLS.
2. ADD P1301 TO MISSING SYMBOLS.
3. DELETE MWC20/7/U5; U/O CA1038; QTY. 18.
4. DELETE MWC20/7/U95; U/O CA1038; QTY. 18.
5. DELETE MWC22/7/U4; U/O CA1038; QTY 10.
6. DELETE MWC22/7/U96; U/O CA1038; QTY 12.
7. DELETE PL189-9S; U/O AX566; QTY 1; SYMBOL P1301.
8. DELETE PO240; U/O A3726; QTY. 1; SYMBOL A1301.
9. DELETE SCFP0632BN6, U/O A3726, QTY. 2.
10. DELETE SCBP0632BN6, U/O A3726, QTY. 2.

TMC SPECIFICATION

NO. S 939

REV:

A

COMPILED: L.G. 5-6-65

CHECKED:

APPD:

SHEET 2 OF 2

TITLE:

CHGR-3 to CHGR-3A CONVERSION

- 11.CHANGE LWEO6MRN QTY.FROM 35 to 33 AND DELETE U/O A3726,QTY.2.
- 12.DELETE CA1038;U/O AX556;QTY 1.
- 13.ADD CA1081;U/O AX556;QTY 1.
- 14.CHANGE ALL CA1038 U/O REFERENCES TO CA1081.
15. ON MWC20/7/UO,CHANGE CA1081 QTY. FROM 70 TO 49, CHANGE TOTAL FROM 72 TO 51
- 16.ON MWC20/7/U3,CHANGE QTY. FROM 36 to 17.
- 17.ON MWC20/7/U1,CHANGE QTY. FROM 119 TO 77.
- 18.ON MWC20/7/U7,CHANGE QTY.FROM 44 TO 26.
- 19.ON MWC20/7/U91,CHANGE QTY. FROM 61 to 51.
- 20.ON MWC20/7/U93,CHANGE QTY.FROM 36 to 15.
- 21.ON MWC20/7/U96,CHANGE QTY. FROM 35 to 18.

C. ON LIST AX547

- 1.CHANGE LAST SYMBOL FROM A1017 to A1016.
- 2.DELETE "DS1006,XDS1006-SEE CHG-3 LIST" FROM MISSING SYMBOLS.
- 3.DELETE"R1065" FROM MISSING SYMBOLS.
- 4.ADD MISSING SYMBOLS R1065,DS1006,XDS1006.
- 5.ON MS2871,CHANGE U/O REFERENCE FROM RR131 to A2946.
- 6.DELETE RR131;U/O A2946;QTY 1;SYMBOL A1017.
- 7.DELETE A4558; U/O A2946; QTY 1.
- 8.DELETE EY102-16; U/O A2946; QTY 1.
- 9.DELETE LD1544/MS6056; U/O A4558; QTY 1.
- 10.DELETE LWEO6MRN; U/O A2946; QTY 2.
- 11.DELETE RC20GF102J; U/O A4558; QTY 1;SYM R1031.
- 12.CHG. RG188/U; U/O A4558 to U/O A2946.
- 13.DELETESCBP0632BN4; U/O A2946; QTY 2.
- 14.CHG. TE111-2; U/O A4558 to U/O A2946.
- 15.CHG. UG625/U; U/O A4558; QTY 2; SYM J1001, J1002 to U/O A2946; QTY 1; SYM J1001.

