

TMC SPECIFICATION

NO. S 949

REV:

COMPILED: L.G. 4/21/65

CHECKED: *L. Gohel 4/21/65*

APPD: *J. Janger*

SHEET 1 OF 2

TITLE: HFRR-2 to HFRR-2A CONVERSION

1. To convert the HFRR-2 to the HFRR-2A, make the following changes.

A. On list HFR-2/HFRR-2

1. Delete BI110-7; U/O A3646; quantity 1; symbol DS1006.
2. Delete LD1523/MS3781; PNL, FRONT
3. Delete MS3781; PNL, FRONT.
4. Delete RC20GF221K; U/O A3646; quantity 1; symbol R1065.
5. Delete TS153-1; U/O A3646; quantity 1; symbol XDS1006.
6. Delete A3646; PNL ASSY, FR.
7. Delete CK769; DIAG, SCHEM.
8. Add LD1804/MS4407; PNL, FRONT; U/O A4234; quantity 1.
9. Add MS4407; PNL, FRONT; U/O LD1804; quantity 1.
10. Add A4234; PNL ASSY, FR; U/O A3762; quantity 1.
11. Add CK961; DIAG, SCHEM; U/O HFRR-2A; quantity 1.
12. Change all U/O references from A3646 to A4234.

B. On list AX512

1. Delete A1301 from last symbols.
2. Add P1301 to missing symbols.
3. Delete MWC20/7/U5; U/O CA898; quantity 15.
4. Delete MWC22/7/U4; U/O CA898; quantity 11.
5. Delete MWC22/7/U96; U/O CA898; quantity 11.
6. Delete PL189-9S; U/O AX512; quantity 1; symbol P1301.
7. Delete P0240; U/O A3726; quantity 1; symbol A3101.
8. Delete PX100-1-294; U/O CA878; quantity 48.
- 8.1 Delete SCFP0632BN6, U/O A3726, quantity 2.
- 8.2 Delete SCBP0632BN6, U/O A3726, quantity 2.
- 8.3 Change LWEO6MRN quantity from 37 to 34 and delete U/O A3726, quantity 2.
- 8.3 Change LWEO6MRN quantity from 36 to 34 and delete U/O A3726, quantity 2.

TMC SPECIFICATION

NO. 5949

REV:

②

COMPILED:

L.G.

CHECKED:

APPD:

SHEET 2

OF 2

TITLE:

HFRR-2 to HFRR-2A CONVERSION

9.Delete CA898;U/O AX512;quantity 1.

10.Add CA1084;U/O AX512;quantity 1.

11.Change all CA898 U/O references to CA1084.

12.On MWC20/7/U0,change CA1084 quantity from 84 to 57,change total from 86 to 59.

13.On MWC20/7/U3,change quantity from 31 to 16.

14.On MWC20/7/U7,change quantity from 47 to 25.

15.On MWC20/7/U93,change quantity from 30 to 14.

16.On MWC20/7/U95,change quantity from 19 to 3.

17.On MWC20/7/U96,change quantity from 32 to 15.

C. On list AX513

1.Change last symbol from A1017 to A1016.

2.Delete "DS1006,XDS1006-see HFR-2 list"from missing symbols.

3.Delete "R1065" from missing symbols.

4.Add missing symbols R1065,DS1006,XDS1006.

5.On MS2871,change U/O reference from RR131 to A3593.

6.Delete RR131;U/O A3593:quantity 1;symbol A1017.

