

TOTAL SHEETS- 3

REVISIONS

REV.	SHEET(S)	DATE	APPR.

USED ON
MODEL- A 10714-7

FOR

MODEL DMC-8

TITLE _____

LAST SYMBOLS

CONSISTS OF
SUPPORTING LISTS

COMPILED _____

CHECKED _____

KEY PUNCHED _____

MISSING SYMBOLS

* NOTE : FOR 75-Ω OUTPUT
SUBSTITUD RRG071R5F (8 REQ'D)
TO RRG0D52R3F

ENGINEERING JOB ORDER

E _____ - _____

§ FOR SPECIAL NOTES,
REFER TO S1200.

MATERIAL LIST

MODEL: DMC-8

SHEET 1 OF 2

PART NUMBER	DESCRIPTION	USED ON	QTY.	QTY. PER UNIT	REFERENCE SYMBOLS	SPECIAL NOTES REFER TO S1200
A10714-7	PRINTED CIRCUIT BD	A10714-7	1			
CC10018	CAP. FXD, MICA	A10714-7	3 4 2	9	C1, C12, C13 C22, C23, C32, C33 C42, C43	
CC10015-X5V104M	CAP. FXD, MICA	A10714-7	3 3 3	9	C2, C52, C53 C62, C63, C72, C73, C82, C83	
CC10017-X5V103M	CAP. FXD. MICA	A10714-7	4	4	C51, C61, C71, C81	
CC10019	CAP. FXD. MICA /	A10714-7	4	4	C11, C21, C31, C41	
CK10780	SCHEM. DIA			1		
CL275-222	COIL. FXD. RF.	A10714-7	4	4	L12, L22, L32, 42	
CL275-221	COIL. FXD RF.	A10714-7	4 4	8	L52, 62, 72, 82 L11, 21, 31, 41	
CL275-330	COIL. FXD. RF.	A10714-7	4	4	L51, 61, 71, 81	
FW02HSS	WASHER, FLAT	A10714-7		16		

MATERIAL LIST

MODEL: DMC-8

SHEET 2 OF 2

PART NUMBER	DESCRIPTION	USED ON	QTY.	QTY. PER UNIT	REFERENCE SYMBOLS	SPECIAL NOTES REFER TO S1200
GL138	COMPOUND, HEAT SINK	A10714-7		X	X	
HD10004	HEAT SINK	A10714-7		8		
LWE02MSS	WASHER LOCK EXT	A10714-7		16		
RC07GF101J	RES, FXD COMP.	A10714-7	4 4	8	R11, 21, 31, 41 R51, 61, 71, 81	
RC07GF332J	" "	A10714-7	4 4	8	R13, 23, 33, 43 R53, 63, 73, 83	
RC07GF432J	" "	A10714-7	4 4	8	R12, 22, 32, 42 R52, 62, 72, 82	
* RN60D71R5F RN60D52R3	" "	A10714-7	4 4	8	R15, 25, 35, 45 R55, 65, 75, 85	
RC32GF221J	" "	A10714-7		4	R54, 64, 74, 84	
RC42GF181J	RES, FXD, COMP.	A10714-7		4	R14, R24, 34, 44	
SCBP0256SS4	SCREW MACH.	A10714-7		16		
TE10023-3	TERM. STUD	A10714-7		20		