

MATERIAL LIST		REV.											MODEL AX-236-S1	
													SHEET 1	OF 1
QUAN. PER UNIT	PART NO.	DESCRIPTION	REF.	ITEM LOCATION			REF. SYMBOLS AND/OR REMARKS							
				USED ON	USED TO MOUNT	QUAN.								
		NOTE: TO MFR. AN AX-236-S1 THE FOLLOW- ING STEPS MUST BE TAKEN												
		1. Get copy of NPL-AX-236	Sheet 5											
		2. Delete MS-1594 & Ref. LD-586	Sheet 5											
		3. Delete LD-586 & Ref. MS-1594	Sheet 19											
		4. Add 1 ea. MS-2844 & Ref. LD-1053	Sheet 5											
		5. Add 1 ea. LD-1053 & Ref. MS-2844	Sheet 19											
		6. Chg. FS-109-3 Quan. from 19 to 13 & Chg. Ref. from (15) MS-1594 to (9) MS-2844	Sheet 10											
		7. Chg. FS-110-1 Quan. from 14 to 9 & Chg. Ref. from (10) MS-1594 to (5) MS-2844	Sheet 10											
		8. Chg. FS-110-7 Quan. from 5 to 4 & Chg. Ref. from (5) MS-1594 to (4) MS-2844	Sheet 10											

Spare
cost of Sales Oct '62

(1) (2) (3) (4) (5) (6)

S/O #	Invoice #	Sales	Totals %	Cost Mat	Total over 1000-	% Cost under 1000
1						
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						

APR-2376

