

51061

TMC SPECIFICATION

NO. S 1061

REV:

Q A

COMPILED:

A. KLEIN
L. GABEL

CHECKED:

LG-1/19/66

APPD:

LG ~~ANA~~

SHEET

1

OF

4

TITLE:

LRCB-1 TO LRCD-1 LIST CONVERSION

A. TO CONVERT THE LRCB-1 TO THE LRCD-1 MAKE THE FOLLOWING CHANGES:

1. Chg all LRCB-1 Refs to LRCD-1.
2. Chg CK977 to CK978; DIAG,SCHEM; u/o LRCD-1.
3. Chg CH479 to CH540; CHART,UNIT BKDN; u/o LRCD-1.
4. Chg S962 to S964; TEST PROC; u/o LRCD-1.
5. Dele 1 ea CA1099; WRG HARN,BRCHD; u/o A5039.
6. Add 1 ea CA1116; WRG HARN,BRCHD; u/o A5039.
7. Deleted
8. Deleted
9. Deleted
10. Dele 1 ea RL156-5; REL,ARM.-6PDT; u/o A5046; Sym K4012.
11. Dele 1 ea TS171-2; SOC,RELAY-W/RET; u/o A5046; Sym XK4012.
12. Chg u/t/m of SCBP0348BN5 from TS171(10) to TS171(9), MS4646(1); u/o A5046.
13. Dele 1 ea WA109-10; WASH.,NM; u/o A5046; u/t/m TS171.
14. Add X ea S404; IRIDITE,YEL; u/o MS4646.
15. Add 1 ea LWS03MRN; WASH.,LK,SPLIT; u/o A5046; u/t/m MS4646 (1).
16. Add 1 ea MS4646; COV,REL CUTOUT; u/o A5046.
17. Add 1 ea 1N2070; SCOND DEV,DIO; u/o A5046; For K4003; Sym CR4020.
18. Dele 1 ea A4435-4; TERM.BD,FNL ASSY; u/o A5047.
19. Add 1 ea A4435-5; TERM.BD,FNL ASSY; u/o A5047.
20. Dele 1 ea 1N2484; SCOND DEV,DIO; u/o A4435-4; Sym CR4017.
21. Dele 2 ea 1N270; SCOND DEV,DIO; u/o A4435-4; Sym CR4014, 4015.
22. Add 1 ea 1N270; SCOND DEV,DIO; u/o A4435-5; Sym CR4017.

TMC SPECIFICATION

NO. S 1061

REV:

A

COMPILED:

CHECKED:

APPD:

SHEET

2

OF

4

TITLE:

LRCB-1 TO LRCD-1 LIST CONVERSION

23. Dele 2 ea RW107-40; RES,FXD,WW; u/o A4435-4; Sym R4004, 4005.
24. Add 1 ea RC42GF271J; RES,FXD,COMP; u/o A4435-5; Sym R4005.
25. Dele 1 ea CE105-50-50; CAP.,FXD,MTLZ P; u/o A4435-4; Sym C4001.
26. Chg all A4435-4 Refs and u/o to A4435-5.
27. Add 1 ea MS4763; BRKT,MTG,REL; u/o A5048; u/t/m RL160-2 (1).
28. Add 2 ea LWE04MRN; WASH.,LK,EXT; u/o A5048; u/t/m MS4763 (2).
29. Add 1 ea RL160-2; REL,ARM.,; u/o A5048; Sym K4013.
30. Deleted
31. Deleted
32. Deleted
33. Add X ea S404; IRIDITE, YEL; u/o MS4763.
34. Deleted
35. Add 2 ea SCFF0440BN5; SCR,MACH; u/o A5048; u/t/m MS4763 (2).
36. Add 2 ea NTH0440BN8; NUT,PLN,HEX; u/o A5048; u/t/m MS4763 (2).
37. Dele 1 ea JJ172; CONN,RECP-BNC; u/o A5045; Sym J4005.
38. Add 1 ea UG657*/U; CONN,RECP-BNC; u/o A5045; Sym J4005.
39. Add 1 ea TE111-2; TERM.,LUG-3/8D; u/o A5045; u/t/m UG657 (1).
40. Add 1 ea WA102-9; WASH.,SHLD-NM; u/o A5045; u/t/m UG657 (1).
41. Add 1 ea WA109-58; WASH,NM; u/o A5045; u/t/m UG657 (1).
42. Dele 1 ea CA1099 and add 1 ea CA1116 w/the following differences:
 - a. Length changes.
 - b. Add MWC20/7/SJ6.
 - c. Add MWC22/7/U3.
 - d. Add MWC22/7/U93.

TMC SPECIFICATION

NO. S 1061

REV:

A

COMPILED:

CHECKED:

APPD:

SHEET

3

OF

4

TITLE:

LRCB-1 TO LRCD-1 LIST CONVERSION

- e. Add MWC22/7/U925.
 - f. Add MWC22/7/U926.
 - g. Add PX100-1-053.
 - h. Dele MWC22/7/SJ8.
 - i. Dele MWC22/7/U98.
 - j. Dele MWC22/7/U824.
 - k. Dele MWC22/7/U921.
 - l. Dele MWC22/7/U934.
-
- 43. Chg A5039 to A5420; LRCD-1 FNL ASSY; including all u/o and u/t/m.
 - 44. Chg A5043 to A5421; CHAS ASSY,MAIN; including all u/o and u/t/m.
 - 45. Chg A5045 to A5422; PL ASSY,REAR; including all u/o and u/t/m.
 - 46. Chg A5046 to A5423; PL ASSY, RELAY; including all u/o and u/t/m.
 - 47. Chg A5047 to A5424; PL ASSY, CTR; including all u/o and u/t/m.
 - 48. Chg A5048 to A5425; SERVO AMPL ASSY; including all u/o and u/t/m.

