TMC SPECIFICATION NO. S-331

COMPILED BY
P. L. K.

TITLE: MSR-1 TEST PROCEDURE

APPROVED P. L. X.

APPROVED P. L. X.

APPROVED P. L. X.

TITLE: MSR-1 TEST PROCEDURE

I. PURPOSE:

The MSR-1, a filter type adapter, when used with any receiv r which provides a nominal 455 KC I.F. output will demodulate AM, SSB, CW and FS signals.

II. DESCRIPTION OF CONTROLS:

A. SIDEBAND

- 1. Manual/Xtal places the lst oscillator in either crystal or variable operation.
- 2. Lower/Upper pilot lights indicate when MSR is set for reception of lower or upper sideband. In the Upper position the 1st oscillator frequency is 472 KC, in the Lower position it is 438 KC.
- Bandspread varies the 1st oscillator when on manual over nominal
 ± 3 KC from its mid frequency.
- C. B.F.O. turns on 2nd oscillator which is at a fixed 17 KC.

D. AVC

- On/Off switch removes AVC control voltage from 1st I.F. amplifier of MSR.
- 2. Slow/Fast switch changes time constant of AVC circuit.
- E. Noise limiter switch in ON position filters pulse noise from both peaks of the audio signal.
- F. Audio Gain varies input to audio output amplifier.
- G. Power switch connects or removes MSR-1 from AC power mains.

DATE 5/11/57 SH. 2 OF 11 COMPILED BY		ТМ	С	SPECIFICATION	NO.	S-331
Pa I.a Ka	TITLE:	MSR-1	TEST	PROCEDURE		JOB
APPROVED A	477					

III. TEST EQUIPMENT REQUIRED:

- A. R.F. signal generator 455 KC
- B. Audio generator
- C. VTVM Hewlett Packard 410 B
- D. AC VTVM Daven or Heath
- E. Battery 0 ± 10 V
- F. 600 ohm 10 watt resistor
- G. .01 mfd 400 V capacitor
- H. Oscilloscope
- I. Eput Counter Mod.

IV. PROCEDURE:

A. POWER SUPPLY

- 1. Continuity check to ground line, cord disconnected. Power switch ON.
 - a. Terminal 2 and 3 of E₂ should be open. Push sideband switch - should be open.
 - b. Terminal 7 of E2 approximately 40 K
 - c. Terminal 8 of E2 approximately 40 K
 - d. Terminal 8 of E1 open
 - e. Terminal 12 of E₁ approximately 1.5 Meg.
 - f. Terminal 10 of E_1

BFO - ON - short

BFO - OFF - .150 K

2. Voltag check - line cord connected to 115 V AC mains.
Power ON.

DATE 5/11/57 SH. 3 OF 11 COMPILED BY	Т	MC	SPECIFICATION	NO.	S-331
P. L. K.	TITLE: MSR-1	TEST	PROCEDURE		JOB
APPROVED DILL A	1				

a. AC voltage-terminal 2 to 3 of E₂ - 115 VAC.

- b. DC voltage-terminal 7 of E2 to ground, + 320 V.
- c. DC voltage-terminal 8 of E2 to ground, + 150 V.

B. Audio Channel Check

1. Controls:

BFO - OFF

Noise Limiter - OFF

Audio Gain - Maximum clockwise

600 ohm 10 watt resistor across terminals 5 and 6 of E_1 AC VTVM across 600 ohm output load.

- 2. Connect audio generator to pin 7 of Vh. Set frequency to 1 KC.
- 3. Adjust input voltage for an output voltage of 24.0 output waveform should just start of clip.
- 4. Measure AC voltage at pin 7 of V7. Should be between 6.5 and 7.5 volts.
- 5. Measure voltage at pin 7 of V6. Should be between .6 and .9 volts
- 6. Switch noise limiter to ON position. Voltage at output load should drop no more than 6 db.
- 7. Measure input voltage at pin 7 of V4. Should be between .l and .15 volts.
- 8. Check frequency response of low pass filter through audio amplifier E input constant at .07 volt at pin 7 of V4.
- 9. Adjust Audio Gain for AC voltage across 600 ohm load of 24.0 volt. Change generator frequency to 17 KC. Output drop across 600 ohm load with constant input should be 55 db or greater.
 If drop is less, then filter requires retuning.

DATE 5/11/57 SH. 1 OF 11	TMC SPECIFICATION N	O. S-331
COMPILED BY	TITLE: MSR-1 TEST PROCEDURE	JOB
APPROVED DILL.	Ast	

10. Connect terminal 1 to 3 of E₁, set generator for maximum undistorted output across terminal 5 and 6. Measure output across 2 and 3 - should be between 0.8 volts and 1.2 volts.

11. Output Hum - remove jumper from 1 and 3 of E₁. Disconnect generator from set. Audio gain fully on - HFO - OFF. Hum voltage across 600 ohm load should be below 60 db.

C. 2ND MIXER OPERATION

- 1. Turn BFO switch ON.
- 2. Measure D.C. bias should be approximately:

V6 pin 2 - 40 VDC

V4 pin 1 - 4.4 VDC

V4 pin 7 - 0

- . If bias is present on pin 7 of V4, adjust tone threshold (R60) until bias becomes zero.
- 3. Tune generator to 17.00 KC. Connect generator to pin 7 of Vl₁
 E in = 5.0 volt.
- 4. Connect oscilloscope to terminal 2 of Z2 low pass filter.
- 5. Tune Zi trimmer to obtain a sero beat pattern on the scope.
- 6. Remove generator. Measure 17 KC across 600 ohm lead with Audio Gain fully on. Should be less than 0.3 volts.
- 7. Turn HFO switch to OFF.
- D. First mixer operation (as amplifier)
 - 1. Connect Audic Generator through .01 mfd capacitor to pin 7 of V_3 (1st mixer).
 - 2. Conne t AC VTVM to pin 1 of V4 (2nd mixer)

DATE 5/14/57 SH. 5 OF 11	TMC SPECIFICATION NO.	S -331
COMPILED BY	TITLE: MSR-1 TEST PROCEDURE	JOB
APPROVED DIK.	A-13	

- Tune generator for peak on meter within range of 17 KC to
 KC. Adjust output to obtain 1.0 wolt on meter.
- 4. Generator input should be approximately .25 to .35.
- 5. Vary generator frequency checking output drop of filt r as follows:

FREQUENCY KC'S	OUTPUT DROP ± 1 DB
17.4	3 db
20.5	3
17.2	6
20.8	6
16.6	45
21.85	45

- E. 1st oscillator (variable) When upper sideband indicator is ON the oscillator center frequency should be 472.00 KC. When lower sideband indicator is ON, the oscillator frequency should be 438.00 KC.
 - 1. Sideband switch set for Upper.
 - 2. Measure bias on pin 1 of V8 should be approximately 11.0 ± 1.0 in both Upper and Lower sideband positions.
 - 3. Connect R.F. signal to pin 7 of V3. Connect CRO to pin 5 of V3.
 - 4. Place reactance balance control in its mid position.
 - 5. Tune generator to 472.00 KC. Tune core of Z3 to obtain z robeat on CRO.
 - 6. Switch sideband to Lower position.
 - 7. Tune trimmer C29 to frequency of 438.00 KC.
- F. 1st Oscillator (crystal)
 - 1. Place corr ct crystals in sockets.

DATE 5/14/57 SH. 6 OF 11 COMPILED BY	TMC SPECIFICATION NO.	S - 331
P. L. K.	TITLE: MSR-1 TEST PROCEDURE	JOB
APPROVED)	AJJ	

Y, - 438.00 KC

Y₂ - 472.00 KC

- 2. Turn manual/Xtal switch to Xtal position.
- 3. Bias on pin 1 of V8 should be between 5.0 V. and 5.5 V. in Upper and Lower positions.
- 4. Measure crystal frequency by zero beat method.

Upper - 472000 ± 50 cps.

Lower - 438000 ± 50 cps.

G. I.F. AMPLIFIER AND 1ST MIXER

- 1. Connect signal generator to I.F. input jack, Jl.
- 2. Connect VTVM HP 410B AC probe to pin 7 of V_3 (1st mixer)
- 3. Set signal generator as follows with unmodulated signal.

AVC - OFF. Check output on pin 7.

Frequency - 450 KC

E In	E Out ± 10%
0.20	1.1
0.50	3.4
1.0	7.0
2.0	13.0

4. Flip AVC switch ON and FAST. Set signal generator as follows at 450 KC:

E In	E Out ± 107	6
0.20	•76	
0.50	1.0	
1.0	1.2	
2.0	1.4	

- 5. AVC Check
 - a. Increase generator input to 1 volt.
 - b. Switch AVC ON in FAST position. Note rate of output drop.

DATE_ 5/14/57 SH7OF_11	TMC SPECIFICATION NO.	S -331
COMPILED BY	TITLE: MSR-1 TEST PROCEDURE	JOB
APPROVED DIK	AJI	

- c. Switch AVC OFF in SLOW position.
- d. Switch AVC ON in SLOW position. Note rate of output drop should be slower than step (b)

H. SENSITIVITY

- 1. Turn BFO ON.
- 2. AVC OFF
- Set signal generator unmodulated to 454 KC to produce a 1 KC note at output.
- 4. Check sensitivity. Manual/Xtal, Upper/Lower

Ein - .05

E out at 600 ohm load - 24.0

I. REACTANCE SHIFT

 Apply DC Supply across 11 and 12 of E₁, set voltage as follows and check frequency of oscillator by zero beat method.
 Adjust reactance balance control to obtain results.

	FREQUENCY SE	IFT ± 10%
CONTROL VOLTAGE	UPPER KC.	LOWER KC.
+ 4.5	+ 4.6	+ 4.0
+ 2.0	+ 2.8	+ 2.3
- 2.0	0 - 2.5	- 2 <u>.</u> 2
- 4.5	- 4.8	- h-1

2. Returne oscillator for 438.00 KC in Lower position and 472.00 KC in Upper position with reactance control voltage set to zero.

J. BANDSPREAD CONTROL

Check shift of oscillator with Bandspread control at ach mark on panel. Reactance control voltage s t to zero.

DATE 5/14/57 SH. 8 OF 11		TN	ИC	SPECIFICATION	NO.	S - 331
COMPILED BY	TITLE:	MSR-1	TEST	PROCEDURE		JOB
APPROVED L	A					

DIAL	UPPER KC	LOWER KC
- 3	= 2.9 to 3.5	- 2.2 to 2.8
- 2	- 2.1 to 2.5	- 1.6 to 3.0
• 1	- 1.0 to 1.2	- 0.8 to 1.0
0	0	0
+1	+ 1.1 to 1.3	+ 0.9 to 1.1
+ 2	+ 2.2 to 2.6	+ 1.8 to 2.2
+ 3	+ 2.9 to 3.3	+ 2.5 to 3.1

K. Sideband Switching Remotely

- 1. Connect D.C. source to 7 and 8 of E₁, with negative lead on 8.
- 2. Vary voltage from sero to minus 9 volts.
- 3. Adjust relay threshold (R54) on rear panel so switching occurs between 7.5 and 8.0 volts.

L. Sideband Tone Generator

- 1. Turn BFO switch to ON.
- 2. Place AC VTVM on pin 7 of V4.
- 3. Set D.C. voltage in at pin 7 and 8 of E_1 to = 5.0 volts.
- 4. Adjust tone threshold (R60) so that Sidetone Oscillator just starts.
 - NOTE: Oscillator will start at two positions fo threshold.

 Correct position produces increased output of oscillator when control voltage goes more negative.
- 5. Decrease control voltage to maximum of 9.0. Oscillator output should increase to 2.5 volts.
- 6. Connect counter on 600 ohm output load.
- 7. Set sideband to Upper position.
- 8. Tune trimmer on Z5 for 2 KC output frequency. Be careful with screwdriver on trimmer screws lot.

DATE 5/11/57 SH. 9 OF 11 COMPILED BY	TMC SPECIFICATION NO.	S-331
	TITLE: MSR=1 TEST PROCEDURE	JOB
APPROVED PLK	ATI	

NOTE: As trimmer is turned clockwise, beat note should ris in pitch.

- 9. Set sideband to Lower position.
- 10. Output frequency should be approximately 500 cps. If below 500 adjust trimmer to obtain 500 cps. Check step (8) again should now be above 2 KC. If the output frequency is higher in Lower position than in Upper, then the leads are reversed on relay.

M. Phone Jack

Plug headset into phone jack. Output should be audible with drop of 2 db across load.

V. FINAL CHECK

- A. Connect speaker across terminal μ and 5 of E_1 .
- B. BFO ON.
- C. Audio Gain as desired.
- D. Signal generator into I.F. input jack J_1 tuned to 455.00 KC.
- E. Sideband on Upper/Manual
 - 1. Tune bandspread control to + position and note audio tone.
 - 2. Tune bandspread control to position and note audio tone.
- F. Sideband on Lower/Manual.
 - 1. Tune bandspread control to + position and note audio tone.
 - 2. Tune bandspread control to position and note audio tone.
- G. Switch sideband to Upper/Xtal
 - 1. Tune signal g nerator 455 KC + audio note
 - 2. Tune signal generator 455 KC audio note

TMC SPECIFICATION NO. S =331

COMPILED BY
P. L. K.

APPROVED

TITLE: MSR=1 TEST PROCEDURE

JOB

H. Switch sideband to Lower/Xtal

- 1. Tune signal generator to 455 KC + audio note
- 2. Tune signal generator to 455 KC audio note
- I. Switch sideband to Upper/Manual
 - 1. Tune signal generator to obtain mero beat.
 - 2. Switch sideband to Lower.
 - 3. No change of sero beat should occur.

DATE 5/11/57 SH. 11 OF 11	TMC	SPECIFICATIO	ON NO.	S331
COMPILED BY	TITLE: MSR-1 TEST	PROCEDURE		JOB
APPROVED Q & K				
SENSITIVITY		REMOTE SELECTION UPPER/LOWER		
SIDEBAND		SIDEBAND INDICATION	IAMPS	
XTAL - UP	PER		UPPER	
- IOWER			LOWER	
			TONE	
MANUAL - UP	PER	-		
- LO	wer	•		
			INMERI	
REMOTE TUNING	- UPPER			
	- IOWER	-		
AVC				
	- SIOW			
	- FAST			
NOISE LIMITER				
AUDIO GAIN				
AUDIO OUTPUI				
PAD				
DATE	······································	TESTED BY		and the second s