TMC SPECIFICATION NO. S 677

TITLE: PROJUCTION TESTING OF THE HFA-1

APPROVED: TITLE: PROJUCTION TESTING OF THE HFA-1

PRODUCTION TESTING OF THE HFA-1

DATE	5/25/62	٠,	
SHEET	2	_OF	

# TMC SPECIFICATION NO. S



677

A.R.F.

CHECKED

TITLE:

PRODUCTION TESTING OF THE HFA-1

APPROVED

### I TEST EQUIPMENT

- A. AC VTVM, Balantine Model 314 (or equivalent)
- B. VTVM, Heathkit V-7A (or equivalent)
- C. 2 RF Generators, Model 82. Measurements (or equivalent)
- D. Audio Generator HP 200 AB (or equivalent)
- E. Power Supply HFP-1.
- F. Counter, HP Model 523 C. (or equivalent)
- G. 2 Resistors, 600 ohms  $\frac{1}{2}$  watt.
- H. 2 Resistors, 50 ohms, 1 watt (BNC termination),
- I. Headphones, 8K ohms.
- J. 2 RG-58/U shorting cables.

#### ADDITIONAL INFORMATION

- A. Block diagram CK-576.
- B. CH-226 and CH-227 voltage and resistance chart.

#### II PRELIMINARY

- A. Inspect the unit for mechanical imperfections such as loose screws, terminal boards, etc.
- B. Inspect for obvious wiring errors.
- C. Check for B+ shorts with an ohmmeter.
- D. Rotate Hum balance pots, R-7000 and R-7051 to mid-position.
- E. Connect a 600 ohm  $\frac{1}{2}$  watt resistor across terminals 10 and 8 of E-7001 and E-7002.
- F. Connect one end of CA-686 to J-7010 on the HFA-1, and the remaining end to J-8005 on HFP-1.
- G. Turn the HFP-1 main power switch to STANDBY position. The green STANDBY light should go on instantaneously.
- H. Turn HFA-1 power switch to the OPERATE position. The HFP-1 yellow TIME DELAY light should go on instantaneously. The HFP-1 red OPERATE light should go on after a period of 30 to 90 seconds. All power for HFA-1 operation is now available. Connect one shorting cable between J7004 & J7005. Connect the other, between J7011 & J7012.

### III PRODUCT DETECTOR AND 250KC ISOLATION AMPLIFIER

- A. Place both channel A and B detection switches in the <u>SSB</u> position, and load switches S-7003 and S-7005 to <u>IN</u> position.
- B. Channel A Product Detector and 250KC isolation amplifier.
  - 1. Connect RF generator to J-7003. Adjust for 250KC and 1 volt out.

DATE /	.:/ <b>5</b> ∕	/25/62	
SHEET_	3_	OF	

# TMC SPECIFICATION NO. S 677



A.R.F.

CHECKED

TITLE:

PRODUCTION TESTING OF THE HFA-1

**APPROVED** 

- 2. Connect the AC VTVM to pin 2 of the product detector V-7003.
- 3. Adjust L-7011 tuning slug to obtain maximum reading (approximately 10 volts). Record on test data sheet.
- 4. Connect AC VTVM across R-7046, and set channel A level. Adjust control to the full CCW position.
- 5. Connect second RF generator to J-7001. Adjust for 250.2KC and 1 volt out. Rotate level adjust CW to obtain OVU reading on the line level meter. The AC VTVM across R-7046 should read 24 volts (1 watt across 600 ohms). Record on test data sheet.
- 6. Disconnect both RF generators. Switch AC VTVM to a low range and adjust R-7000 (channel A hum balance control) for minimum reading (Approx. 50 db). Reconnect RF generators.
- 7. Reduce 250.2KC input at J-7001 to .76 volts, and rotate Channel A level adjust CW to obtain OVU on line level meter again. This is to insure sufficient gain in the amplifier for a reduced IF input due to AGC action.

## C. Channel A RCC input

- 1. Disconnect RF input from J-7003 and reconnect to J-7009, the 250KC RCC input jack. The reading on the Channel A WU meter should disappear. Record on test data sheet.
- 2. Connect a jumper between the B+ 200 volt line and the + side of the relay coil on K-7000; activation of K-7000 should occur, and a OVU reading on the Channel A line to level meter should appear
- D. Channel B Product Detector and 250KC Isolation Amplifier
  - 1. Repeat part III B 1.
  - 2. Repeat part III B 2 using V-7011.
  - 3. Repeat part III B 3 using L-7012.
  - 4. Repeat part III B 4 using R-3097 and channel B level adjust control.
  - 5. Repeat III B 5 using J-7008, and the RF VTVM across R-7097.
  - 6. Repeat III B 6 using R-7051 (channel Bhum balance control)
  - 7. Repeat III B 7 using J-7008 and Channel B level adjust.

#### E. Channel B RCC Input

- 1. Disconnect RF input from J-7003, and reconnect to J-7009, the 250KC RCC input jack. The reading on the Channel B' VU meter should disappear.
- 2. Repeat part III C 2 using Channel B line level meter.

3.7 %

DATE 3/26/62 SHEET 4 OF		TMC SPECIFICATION NO. S 677
A.R.F. COMPILED	CHECKED	TITLE: PRODUCTION TESTING OF THE HFA-1

**APPROVED** 

### IV CHANNEL A BFO AND PHONES MONITOR

- A. Place detection switches S-7002 and S-7004 in the CW position.
- B. Rotate Channel A BFO tuning capacitor C-7053 to the OKC front panel position. The capacitor should be meshed half way or at mid-capacity.
- C. Adjust capacitors C-7006, C-7008, C-7032, and C-7030 to mid-capacity.
- D. Connect the counter to pin 2 of the isolation amplifier V-7001. The counter reading should be in the vicinity of 250KC.
- E. Rotate the BFO tuning capacitor to -5KC and adjust C-7006 to obtain approximately a 254.2KC reading on the count r.
- F. Rotate the BFO tuning capacitor to the +5KC position, and adjust C-7008 to obtain approximately a 245.8KC reading on the counter.
- G. Repeat steps IV E and F until one even deviation from the center frequency (250KC) is obtained. The deviation should be at least 4.2KC or greater. Disconnect counter and record deviation obtained on test data sheet.
- H. Connect RF generator to J-7001. Adjust for  $250KC \pm 2$  yeycle and 1 volt out.
- I. Rotate the level adjust control to obtain OVU on the line level meter, and connect the AC VTVM across R-7046. The' VTVM should yield a reading of 24 volts + 2 volts. Record on test data sheet.
- J. Rotate the BFO tuning capacitor from -5KC to +5KC. The VU meter should not vary more than 1 VU; (except at 0 where the meter drops towards 0). Record on test data sheet.
- K. Insert earphones into the phones jack, J-7006, and place the monitor pot, R-7041 in the full CW position.
- L. A changing beat note, approximately 20-4,200 cps. should be heard during rotation of the BFO tuning capacitor.
- M. Connect the AC VTVM to the slider of R-7041, (the monitor gain pot). A reading of 2.2 volts +.5V should be obtained. Record on test data sheet.

# V CHANNEL B BFO AND PHONES MONITOR

- A. Repeat IV B with C-7029.
- B. Repeat IV D with V-7009.
- C. Repeat IV E adjusting C-7030.
- D. Repeat IV F adjusting C-7032.
- E. Repeat IV G using C-7032 and C-7030.
- F. Repeat IV H using J-7008.
- G. Repeat IV I WIN VTVM across R-7097.

DATE_5/25/62	_
SHEET 5 OF	

# TMC SPECIFICATION NO. S 677



A.R.F.

CHECKED

PRODUCTION TESTING OF THE HFA-1

APPROVED

- H. Repeat IV J.
- I. Repeat IV K using J-7013 and R-7096.
- J. Repeat IV L.
- K. Repeat IV M using R-7096.

## VI CHANNEL B ISOLATION AMPLIFIER

- A. Connect 50 ohm 1 watt termination to the Channel A and B IF output jacks, J-7000 and J-7007 respectively.
- B. Connect the AC VTVM across the J-7007 termination and adjust T-7004 slug for maximum indication. The reading should be 1 volt or better. Record on test data sheet.

# VII CHANNEL A ISOLATION AMPLIFIER

- A. Remove RF generator input from J-7008 and connect to J-7001.
- B. Connect AC VTVM across J-7000 termination and adjust T-7000 slug for maximum indication. The reading should be 1 volt or better. Record on test data sheet.

# VIII CHANNEL A AND B AM DETECTOR

- A. Rotate detection switches, to the AM position.
- B. Insert .6 volts of 250KC, 50% modulated with 1KC, to J-7001. Connect AC VTVM across R-7046 load resistor and rotate Channel A level adjust to obtain 0VU on the associated line level meter. The VTVM shoulds show 24 volts. Record on test data sheet.
- C. Repeat VIII B using J-7008, and Channel B level adjust and R-7097 load resistor.
- D. Addio Sync Tone
  - A. Insert 2KC of audio signal at 6 volts into J-7002.
  - B. Temporarily connect a jumper clip lead between ground and grounding black lead of relay K-7001. This lead is connected to pin P of J-7010. OVU on the Chann 1 A line level meter should be present. Record on test data sheet.

DATE 5/25/62 SHEET 6 OF 6		TMC SPECIFICATION NO. S 677	A
A.R.F.	CHECKED	TITLE:	
APPR	OVED		

# THE TECHNICAL MATERIEL CORPORATION MAMARONECK, N. Y.

# HFA-1 TEST DATE SHEET

SERIAL NO.	
MFG. NO.	
Thannel A - 250KC isolation amplifier  Product detector  Hum balance  PCC input  Channel B - 250KC isolation amp.	Volts
Channel B - 250KC isolation amp.  Product detector  Hum balance  RCC input	Volts
Channel A - BFO KC deviation BFO audio output BFO VU deviation Phones monitor audio	Volts VU Volts
Channel B - BFO KC deviation BFO Sudio output BFO VU deviation Phones monitor audio	Volts VU Volts
Channel B - Isolation Amplifier Channel A - Isolation Amplifier	Volts Volts
Channel A - AM Detector audio Channel B - AM Detector audio Audio Syne tone	Volts
DATE	
TESTER	

D	V	1 (	1	n	М	*	u		Ŧ

# THE TECHNICAL MATERIEL CORP. MAMARONECK NEW YORK

S-677

			<u> </u>	MAMARONECK NEW YORK		
MODEL	HFA=	1		PROJECT NO		
DATE	REV.	PAGE	EMN#	DESCRIPTION	снк.	APP.
9/6/62	A	2	7209	On Test Equip. Sect., add letter "J"; 2 RG-58/U	1	
				shorting cables		
				On Preliminary Sect., add to letter "H"; connect one	\ \ \ / T	
				shorting cable between J7004 & J7005, connect the		
				other between J7011 & J7012		1
		3		On Product Detector Sect., On No. 6, add(approximately	\ <del>\</del>	11/
				50 db) between the words "Reading & Reconnect"	1	
		4		On Channel A BFO Sect., on letter "J" add; Except	1	
				at 0 where the meter drops towards 0"	7	
				On letter "M" Chg. +.5 to +.5V	7	
4/23/64	В	2	11283	On sht 2 line 2, h; CHANGED STANDBY TO OPERATE		K
					-	
						-
					$\neg \uparrow$	
	$-\!\!\perp$					
			·			