



# MATERIAL LIST

REV

Q A

MODEL PVR-2

SHEET 1 OF 4

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION ELECTRICAL/MECHANICAL	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
1	CU-113		1	Clamp, BX Fitting				
4	CU-126-B		1	Furrule, Handle				
2	HA-102-2-BN		2	Handle				
1	MS-2153		4	Panel				
1	PL-100		1	Connector, Plug, AC, Female		CA-605-2	1	P3
1	PL-218		1	Connector, Plug, AC, Male		CA-575-11	1	P2
1	PL-176		1	Connector, Plug, AC, Female		CA-555-8	1	P1
1	TF-209		8	Transformer, Volt, Regulator				T1

**MATERIAL LIST**

REV

Ø A

MODEL PVR-2

SHEET 2 OF 4

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION HARDWARE	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
4	LWE1OMRN		1	Lockwasher, Ext.				Handle, Mtg.
4	SCBS1032BN10		1	Screw, Machine				Handle, Mtg.
4	SCBS2520BN12		1	Screw, Machine				Xfmr, Mtg.

# MATERIAL LIST

REV

Q A

MODEL PVR-2

SHEET 3 OF 4

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION RAW MATERIALS	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
42"	WI-132		1	Cable, AC		CA-605-2		
2	WI-134-6-5		1	Cable, AC		CA-555-8 CA-575-11	1 1	

**MATERIAL LIST**

REV

QA

MODEL PVR-2

SHEET 4 OF 4

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION SUPPORTING DRAWINGS	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
1	CA-555-8		2	Cable, AC, Output				WI (P 1)
1	CA-575-11		1	Cable, AC, Input				W2 (P 2)
1	CA-605-2		1	Cable, AC, Fan, 42 in.				W3 (p 3)

