

TRANSFORMER, RF, FIXED

MODEL TR137

REV B

TITLE

USED ON

MODEL SECTION

HFD-1

HFD-2

LIST SECTIONS

SHEET NO.

1. SUPPORTING NOTES
2. SUPPORTING LISTS
3. ELECTRICAL/MECHANICAL
4. SUPP ASSY/REF DWGS
5. SPECIFICATIONS
6. LOOSE ITEMS
7. PARTS PECULIAR

SEE BELOW

NONE REQ

1

2

SEE NOTE 2

NONE REQ

NONE REQ

LAST SYMBOLS

COMPILED R. HAY

NONE

CHECKED J. SABATINO J.S.

APPROVED R. HAY

FNL APPR

ISS DATE

MISSING SYMBOLS

NONE

NOTE 1. THE FOLLOWING SYMBOL, #, IN THE REMARKS COLUMN INDICATES THAT THE PART NUMBER IMMEDIATELY FOLLOWING IT IS THE TMC PROPRIETARY MANUFACTURING DRAWING FOR THE CORRESPONDING NUMBER IN THE PART NUMBER COLUMN.

NOTE 2. SEE DWG A1244 FOR TEST DATA.

NOTE 3. FOR GL10002, USE 165 GRAMS OF RESIN.

MATERIAL LIST

REV

B

MODEL TR-137

SHEET 1 OF 2

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION ELECTRICAL/MECHANICAL	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
	BS100			SOLDER, TIN ALY		A1244		
1	CI10001-2			CORE, TOROID		A1244	1	
	GL10001			ADHESIVE		A1244		
	GL10002			COMPOUND, POTTING	SEE NOTE3	A1244		
1	PX312			TERM. BD	NO DWG	A1132	1	
6	TE145			TERM. , LUG, CLINCH		A1132	6	
64	WI10007-1			WIRE ,ELEC ,MAG	SZ 30	A1244	64	
2	WL100-4			WIRE ,ELEC ,BUSS	SZ 16	A1244	2	

MATERIAL LIST

REV

B

MODEL

TR137

SHEET

2

OF

2

QUAN. PER UNIT	PART NO.	DWG. REV.	DWG. SIZE	DESCRIPTION SUPP ASSY/REF DWGS	REF.	LOCATION		SYMBOLS
						USED ON	QUAN.	
1	A1132			TERM. BD ASSY		A1244	1	
1	TR137			XFMR, RF, FXD	#A1244	TR137	1	

